



KenGen

KENYA ELECTRICITY GENERATING COMPANY PLC

**TENDER FOR SUPPLY OF DRILL STRING INSPECTION AND REPAIR SERVICES FOR
GEOHERMAL DEVELOPMENT DEPARTMENT.**

RFx: 5000010880

KGN-GDD-085-2022

OPEN INTERNATIONAL

Date: 5th October 2022

CLARIFICATION No. 1

In accordance with the **Tender for Supply of Drill String Inspection and Repair Services for Geothermal Development Department**, KenGen hereby issues **Clarification No.1.**

No.	Bidder's Question	KenGen's Response
1	The rethreading and hard banding of Rotary Shouldered Connections (RSC) is generally a specialized service and there specific local companies that provide these services and we request that evaluation of these specific services be evaluated, where applicable, through Specialized Sub Contractors, as proposed by the respective bidder(s). These is to be evidenced by documents submitted by the nominated specialized sub – contractors	KenGen will only deal with the main bidder. Evaluation of the local rethreading facility and the hard banding unit shall be as per technical criteria, TR9. Due diligence will also be conducted on the nominated local rethreading facility and hard banding equipment.

ACKNOWLEDGEMENT OF CLARIFICATION NO. 1

We, the undersigned hereby certify that the clarification is an integral part of the document and the alterations set out in the clarification has been incorporated in the tender proposal.

Signed.....

Tenderer.....

Date.....